



WARNING!!!

B&M replacement Ford flexplates #50238 & #50239 will not properly balance 351CID engines. The #50238 & #50239 flexplates are only to be installed onto 1982 and later 302 CID engines requiring 50 inch per ounce balance weight.

9100285



WARNING!!!

B&M replacement Ford flexplates #50238 & #50239 will not properly balance 351CID engines. The #50238 & #50239 flexplates are only to be installed onto 1982 and later 302 CID engines requiring 50 inch per ounce balance weight.

9100285



WARNING!!!

B&M replacement Ford flexplates #50238 & #50239 will not properly balance 351CID engines. The #50238 & #50239 flexplates are only to be installed onto 1982 and later 302 CID engines requiring 50 inch per ounce balance weight.

9100285